

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2023

Submitted Date:

11/28/2023

Document Number:

698601289**FIELD INSPECTION FORM**Loc ID 338162 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris	970-330-7034	smithenergy@live.com	
Smith, Glenn	970-330-7034	gsmithten@what-wire.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293288	WELL	PR	12/13/2007	GW	125-11040	MONK 4-18	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign at well location was laying on the ground at time of inspection. Emergency contact sticker needs to be replaced.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at remote Gas Meter Run. Stickers are peeling off and need to be replaced.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank. Stickers are peeling and need to be replaced.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on both the Well location and Meter Shed signs.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing at well location is laying on ground at time of inspection.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located at shared location on CR 51. Gas Meter Run. Chart in Meter Box dated 10-31-23. Meter Calibration/Test Log dated 7-25-22. Well Inlet Valve open. Gas Outlet Valve open.  Gas meter is over due calibration.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	12/29/2023

Type: Bradenhead	# 1	
Comment:	Bradenhead plumbed to surface.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Separator Shed at remote Gas Meter Run.	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:	Located at remote Gas Meter Run.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Meter Shed at remote Gas Meter Run.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV PLASTIC		,
Comment:	Tank is partially collapsed/dented on one side. Hatch is missing cover. Tank is empty and does not appear to be in use at time of inspection.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	24 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 293288	Type: WELL	API Number: 125-11040	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Electronic Well File reflects last Production/Status reported 9/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601322	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336304">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336304</a>