

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 1 – Skim Tank – NFPA Label missing**

**Photo 2 – Skim Tank – NFPA Label missing**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 3 – Pit Area – Looking West**

**Photo 4 – Pit Area – Looking East**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 5 – Pit Area – Looking South**



**Photo 6 – South Crude Oil Tanks**

Inspection Photos  
Location Name: Henderson #1  
Location ID: 331730



Energy and Carbon Management Commission  
40.58345, -103.73594, 4587.9ft  
11/21/2023 13:55:54



Energy and Carbon Management Commission  
40.58344, -103.73594, 4591.1ft  
11/21/2023 13:56:03

Photo 7 – Tank Battery Sign – 24-Hour Emergency Phone Number no longer visible

Photo 8 – South Crude Oil Tanks

Inspection Photos  
Location Name: Henderson #1  
Location ID: 331730





Photo 9 – North Crude Oil tanks

Photo 10 – Risers not marked with OOSLAT

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 11 – Risers not marked with OOSLAT**



**Photo 12 – Risers not marked with OOSLAT**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 13 – Riser East of Heater Treater not marked with OOSLAT and Stained Soil**

**Photo 14 – Heater Treater**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 15 – Unused Heater Treater and Gas Meter House  
have been removed**

**Photo 16 – Pumping Unit**

Inspection Photos  
Location Name: Henderson #1  
Location ID: 331730



Photo 17 – Wellhead



Photo 18 – Stained Soil at Wellhead