

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7592 From entrance to location



Photo # 7593 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7594 Location



Photo # 7595 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7596 Location



Photo # 7597 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7598 No cal card/meter calibration info not conspicuously posted



Photo # 7599 No cal card/meter calibration info not conspicuously posted

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7600 No cal card/meter calibration info not conspicuously posted



Photo # 7601 Open ended load line

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7602 Hole in liner/liner needs maintenance



Photo # 7603 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7604 Production tank not properly labeled/missing required information



Photo # 7605 Production tank not properly labeled/missing required information

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7606 Production tank not properly labeled/missing required information



Photo # 7607 Debris