

Inspection Photos

API: 061-06403

Operator: STRACHAN EXPLORATION INC

Inspection Date: 11/29/2023



Inspection Photos



Photo 1. Facing toward the offsite tank battery location.



Inspection Photos



Photo 2. The sign is faded and does not meet the signage requirements of Rule 605.e. Previous corrective action was not completed.



Inspection Photos



Photo 3. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Previous corrective action was not completed.



Inspection Photos



Photo 4. There is oil stained soil at the back side of the tank that needs to be cleaned up.



Inspection Photos



Photo 5. Facing southwest toward the wellsite..



Inspection Photos



Photo 6. Facing toward the tank. The berm around the tank is inadequate to contain a spill. The fence around the tank is in disrepair. Previous corrective action was not completed.



Inspection Photos



Photo 7. The well sign is faded and does not meet the signage requirements. Previous corrective action was not completed.

