

Inspection Photos

API: 061-06394

Operator: STRACHAN EXPLORATION INC

Inspection Date: 11/29/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the offsite tank battery location. This tank at red arrow is not in use and needs to be removed. Previous corrective action was not completed.



Inspection Photos



Photo 2. The fence around the tank is inadequate to prevent livestock entry and is not maintained. The berm around the tank is insufficient to contain a spill (150% of tank capacity) and has animal burrows the sides. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06394 | Date: 11/29/2023

Inspection Photos



Photo 3. Netting was installed on the open top tank.



Inspection Photos



Photo 4. There is unused disconnected pipe that needs to be removed.



Inspection Photos



Photo 5. Facing northwest toward the wellsite.



Inspection Photos



Photo 6. There is stained soils where exhaust is being blown on to the ground.



Inspection Photos



Photo 7. There is oily fluid in the containment next to the pump jack. Oily fluid has spilled onto the ground and needs to be cleaned up. Previous corrective action was not completed.

