

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2023

Submitted Date:

11/28/2023

Document Number:

698601292

**FIELD INSPECTION FORM**Loc ID 303800 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glenn	970-330-7034	gsmithten@what-wire.com	
Smith, Chris	970-330-7034	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253617	WELL	PR	04/01/2017	GW	125-07495	MONK 1-18	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank. Sticker is peeling and needs to be replaced.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign located inside well fencing. Sticker is peeling and needs to be replaced.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign, meter shed sign, and tank sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well site.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Separator/Meter Shed at remote Gas Meter Run.		
Corrective Action:		Date:	

Type: Vertical Separator	# 1		
Comment:	Located at remote gas meter location.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 51. Gas Meter Run. Chart in Meter Box dated 10-31-23. Meter Calibration/Test Log dated 7-28-22. Well Inlet Valve open. Gas Outlet Valve open.		
	Gas meter is overdue calibration.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 12/29/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)	24 BBLS				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	253617	Type:	WELL	API Number:	125-07495	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Electronic Well File reflects last Production/Status reported 9/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403608201	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336473</a>
698601325	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336461">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336461</a>