

Inspection Photos

API: 061-06271

Operator: SAMSON OIL COMPANY

Inspection Date: 11/29/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the fenced location. The location has been mowed.



Inspection Photos



Photo 2. Center of the location facing northwest. This area has no vegetation growth which indicates impacted soils.



Inspection Photos



Photo 3. Facing southeast at the location. This area has no vegetation growth which indicates impacted soils.



Inspection Photos



Photo 4. Center of the location facing east. There are undesirable weeds throughout most of the location. The vegetation has been mowed but further weed control will need to be conducted.



Inspection Photos



Photo 5. Drone aerial photo facing west toward the location. Taken 8/24/2023



Inspection Photos



Photo 6. Drone aerial photo facing west down toward the location. The reddish brown vegetation is undesirable weeds (Kochia). The desirable vegetation has not re-established and there are bare areas with no vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06271 | Date: 11/29/2023

Inspection Photos



Photo 7. Drone aerial photo facing east down toward the location. The reddish brown vegetation is undesirable weeds (Kochia). The desirable vegetation has not re-established and there are bare areas with no vegetation. The bare area appears to be impacted soil from the wellsite. Taken 8/24/2023



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06271 | Date: 11/29/2023