

# Inspection Photos

API: 061-06366

Operator: SAMSON OIL COMPANY

Inspection Date: 8/24/2023



## Inspection Photos



**Photo 1.** Drone aerial photo facing south toward the former access road and location. The perennial vegetation along the access road has re-established.



## Inspection Photos



**Photo 2.** Drone aerial photo facing south toward the location. The green and reddish vegetation is undesirable weeds (Kochia) The desirable vegetation has not re-established.





## Inspection Photos



**Photo 3.** Drone aerial photo facing north toward the location. The green and reddish vegetation is undesirable weeds (Kochia) The desirable vegetation has not re-established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 061-06366 | Date: 8/24/2023



## Inspection Photos



**Photo 4.** Closer view of the location and tall undesirable weeds (Kochia) which needs to be controlled. The fence installed does not completely surround the entire location.

