

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2023

Submitted Date:

12/05/2023

Document Number:

696305464

FIELD INSPECTION FORMLoc ID 437037 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437036	WELL	SI	08/01/2023	OW	123-39389	Pronghorn 11-41-24HNC	TA
438544	WELL	SI	11/01/2021	OW	123-40034	Pronghorn C-W-24HNB	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	500 BBL Produced Water Tank NFPA and Capacity Labels; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/08/2024
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	O-W-24HNB disconnected flowline riser not OOSLAT. See photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	01/08/2024
Type	DEBRIS		
Comment:	Tumbleweed Debris at Pipe Rack; see photos		
Corrective Action:	Comply with Rule 606	Date:	01/08/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	TA Wellheads		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	500 BBLS	STEEL AST		40.389510,-104.164720

Comment:				
Corrective Action:				Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 437036 Type: WELL API Number: 123-39389 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Wellhead found in TA Status at the time of this Inspection. Last Production reported 10.01.2022

Corrective Action: _____ Date: _____

Facility ID: 438544 Type: WELL API Number: 123-40034 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Wellhead found in TA Status at the time of this Inspection. Last Production reported 10.01.2021
Shut-In date 11.01.2021
Well has been Shut-In/Temporarily Abandoned for 2-Years not MIT on FileCorrective Action: Perform MIT per Rule 417.b
Submit Form 4 requesting TA status. Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Water Tank Labels per Rule 605.h Tumbleweed Debris at Pipe Rack per Rule 606 Riser at C-W-24HNB not OOSLAT per Rule 1105 C-W-24HNB not MIT of File per Rule 417.b	petrie	12/05/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305465	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6344799