

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/05/2023

Document Number:

713300345

FIELD INSPECTION FORMLoc ID 317708 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		randy.silver@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239827	WELL	PR	10/01/2021	OW	123-07615	COSSLETT 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Both new sign on site have wrong API number Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/05/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	cal date 11-23		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	pped to surface	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	electric motor	
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	electrical panels and automation	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shared with crude tank			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-07615
123-09303

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 239827 Type: WELL API Number: 123-07615 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: appears to be shut in at inspection timeCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/06/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary
 On Tuesday, 12-5-2023 at approximately 14:00, I, Inspector Michael Kester, conducted an on-site inspection.
 Location: Cosslett 1
 Operator: KPK
 API#: 123-07615
 County: Weld
 While there, I observed well site with pumping unit with production equipment.
 During this inspection the following possible compliance issues were observed:
 Sign, Rule 605d, corrective action date 1-5-2024
 Weather conditions: sunny and dry
 A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with ECMC rules.
 This is a summary of inspection report.

kesterm

12/05/2023

This inspection does not nullify any orders or NOAV from the ECMC
 This is a continuing education inspection

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300346	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6346698