

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/05/2023

Document Number:

713300347

FIELD INSPECTION FORMLoc ID 318531 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241514	WELL	PR	08/01/2023	OW	123-09303	COSSLETT 2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Faded unreadable Sign not posted or information inaccurate at well		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/05/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	electrical panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 241514 Type: WELL API Number: 123-09303 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: at time of inspection well appeared to be shut inCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/11/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary
 On Tuesday, 12-5-2023 at approximately 15:00, I, Inspector Michael Kester, conducted an on-site inspection.
 Location: Cosslett 2
 Operator: KPK
 API#: 123-09303
 County: Weld
 While there, I observed well site with pumping unit with production equipment. During this inspection the following possible compliance issues were observed:
 Sign, Rule 605d, corrective action date 1-5-2024
 Weather conditions: sunny and dry
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.
 This is a summary of inspection report.

kesterm

12/05/2023

This inspection does not nullify any orders or NOAV from the ECMC
 This is a continuing education inspection

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300348	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6346699