

Inspection Photos
Location Name: UPRR_HABEL_1-35
Location ID: 319728



Photo #1 Tanks.



Photo #2 Weeds throughout location.

Inspection Photos
Location Name: UPRR_HABEL_1-35
Location ID: 319728



Photo #3 Berm eroded under crude tank.



Photo #4 Stained soil.

Inspection Photos
Location Name: UPRR_HABEL_1-35
Location ID: 319728



Photo #5 Separator.



Photo #6 Pump jack.