

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/30/2023

Document Number:

708700043**FIELD INSPECTION FORM**Loc ID 320852 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	Owner

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205239	WELL	PR	12/01/2022	OW	007-06117	NIELSEN 4	EI
320852	LOCATION	AC	12/01/2022		-	NIELSEN-N32N1E 18NENE	EI

General Comment:

Valve on wellhead was leaking methane gas during inspection. Phone call was made to phone number listed on lease sign on 11/15/2023. Operator did not answer and voicemail was left notifying of leak and requesting operator contact this inspector. As of issuance of this inspection the operator has yet to contact inspector.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Alleged violation.Operator does not monitor emergency number listed on lease sign posted on location in violation of Rule 605.a.(3)Corrective Action: Operator shall monitor emergency contact number at all times as required per rule.Date: 12/01/2023Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: NoComment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	<u>Wellhead valve shown in attached photo was leaking methane during inspection.</u>		
Corrective Action:	<u>Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.</u>	Date:	<u>12/01/2023</u>

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 205239 Type: WELL API Number: 007-06117 Status: PR Insp. Status: EIFacility ID: 320852 Type: LOCATION API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403610775	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338828
708700044	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338813
708700045	Leaking valve	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338814
708700046	Gas monitor alarm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338815