

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2023

Submitted Date:

12/01/2023

Document Number:

707602124

FIELD INSPECTION FORMLoc ID 414330 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414323	WELL	TA	01/01/2022	OW	123-30730	TREBOR B 11-18	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs
(326889, 326886, 414330, 414332, 414334).

(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs
(310601, 323768).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference:

A.) Field Inspection Report doc. #707602120 and/or Location ID #326889
for TA Well(s) info.B.) Field Inspection Report doc. #707602122 and/or Location ID #326886
for TA Well(s) info.C.) Field Inspection Report doc. #707602124 and/or Location ID #414330
for TA Well(s) info.D.) Field Inspection Report doc. #707602126 and/or Location ID #414332
for TA Well(s) info.E.) Field Inspection Report doc. #707602129 and/or Location ID #414334
for TA Well(s) info.F.) Field Inspection Report doc. #707602131 and/or Location ID #310601
for PA Well(s) info.G.) Field Inspection Report doc. #707602133 and/or Location ID #326889
for Battery / Facility, Equipment info.

Location					
Lease Road:					
Type	Access				
comment:	Adequate				
Corrective Action					Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance.				
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.				Date: <u>01/02/2024</u>
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Iron panel. Wellhead guard needs maintenance. Panels loose.				
Corrective Action:					Date:
Equipment:					
				corrective date	
Type: Other	# 1				
Comment:	Wellhead: w/ Master, casing valves.				
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

		CENTRALIZED BATTERY		40.416741,-104.523329	
Comment:	<p>Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p>				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 414323 Type: WELL API Number: 123-30730 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Battery: Inactive | Shut-down.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last production: 04/2020.

Form 4 on file. TA date: 10/30/2021. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 11/03/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/01/2020. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/09/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 11/29/2023 at approximately 14:47 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR B/11-18 Location ID: 414330 Well Name(s): Trebtor B 11-18. API: 123-30730. Location County: Weld County, Colorado Weather: Mostly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (310601, 323768). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info. B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info. C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info. D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info. E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info. F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info. G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/01/2023
<p><u>Attached Documents</u></p> <p>You can go to COGCC Images (https://cogcc.state.co.us/webblink/) and search by document number:</p>		

Document Num	Description	URL
403612663	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341066
707602125	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341044

