

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8767 From entrance to location



Photo # 8768 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8769 Location



Photo # 8770 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8771 Location



Photo # 8772 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8773 Location



Photo # 8774 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180




Photo # 8775 Location



Photo # 8776 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



**Photo # 8777 Methanol tank improperly labeled/lacks required information/has inaccurate information**



**Photo # 8778 Methanol tank improperly labeled/lacks required information/has inaccurate information**





**Location ID: 334180**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180




Photo # 8781 Debris



Photo # 8782 Wellhead lacks signage



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



**Photo # 8783 PRV & rupture disc vent lines terminate in an unsafe manner**



**Photo # 8784 PRV & rupture disc vent lines terminate in an unsafe manner**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8785 Open ended load line



Photo # 8786 Open ended load line