

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 31 6S93W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8615 Lack of stabilization/compaction/insufficient BMP's



Photo # 8616 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8617 Lack of stabilization/compaction/insufficient BMP's



Photo # 8618 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8619 Lack of stabilization/compaction/insufficient BMP's



Photo # 8620 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8621 Lack of stabilization/compaction/insufficient BMP's



Photo # 8622 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8623 Lack of stabilization/compaction/insufficient BMP's



Photo # 8624 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8625 Lack of stabilization/compaction/insufficient BMP's



Photo # 8626 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8627 Lack of stabilization/compaction/insufficient BMP's



Photo # 8628 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8629 Lack of stabilization/compaction/insufficient BMP's



Photo # 8630 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8631 Lack of stabilization/compaction/insufficient BMP's



Photo # 8632 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8633 Lack of stabilization/compaction/insufficient BMP's



Photo # 8634 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8635 Drain needs maintenance



Photo # 8636 Drain needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 8637 Drain needs maintenance