

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403604514

Date Received:

12/12/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Nikola Welch

903-806-1309

nwelch@vaqueroenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902233

Inspection Date: 11/14/2023

FIR Submit Date: 11/14/2023

FIR Status: _____

Inspected Operator Information:

Company Name: MUSTANG RESOURCES LLC

Company Number: 10550

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

LOCATION - Location ID: 311543

Location Name: CLOUGH FEDERAL-66S94W Number: 14SESW County: _____

Qtrqtr: SESW Sec: 14 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.520029 Longitude: -107.858619

FACILITY - API Number: 05-045-00 Facility ID: 311543

Facility Name: CLOUGH FEDERAL-66S94W Number: 14SESW

Qtrqtr: SESW Sec: 14 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.520029 Longitude: -107.858619

CORRECTIVE ACTIONS:

1 CA# 188200

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 11/17/2023

Response: CA COMPLETED

Date of Completion: 11/22/2023

Operator
Comment:

Rupture disk has been replaced and vent has been capped. Please see supporting picture.

COGCC Decision: _____

COGCC
Representative:

2 CA# 188201

Corrective Action: Operator needs to install & calibrate their own meter or have TEP calibrate existing meter on location to comply with CECMC rules.

Date: 12/14/2023

Response: CA COMPLETED

Date of Completion: 12/04/2023

Operator Comment: Meters are owned and operated by Terra Energy Partners. Meter calibration completed on 12/4/2023. Please see supporting documents.

COGCC Decision:

COGCC
Representative:

3 CA# 188202

Corrective Action: Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/22/2023

Operator Comment: Please see supporting documents that show a drain hole in the vent on the PRV, therefore maintaining "free of water and debris".

COGCC Decision:

COGCC
Representative:

4 CA# 188203

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 11/29/2023

Response: CA COMPLETED

Date of Completion: 11/28/2023

Operator Comment: Please see supporting documents that show Storm water issues have been resolved

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action resolution provided

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nikota Welch

Signed: _____

Title: Regulatory Manager

Date: 12/12/2023 2:37:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403606970	Terra Energy Partner Meter Card Information
403606993	Rupture Disk & Vent
403607000	Drain Hole in the Vent
403616450	Storm Water Picture 1
403616453	Storm Water Picture 2
403616464	Calibration Card

Total Attach: 6 Files