

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Location Overview: Location is within Black Bear/High  
Priority/Density Habitat areas.**

**Section/Township/Range: 1 7S94W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9269 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9270 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9271 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9272 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9273 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9274 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9275 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9276 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9277 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9278 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9279 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9280 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9281 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9282 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9283 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9284 Lack of stabilization/compaction/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad**  
**Location #: 334667**



**Photo # 9285 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9286 Lack of stabilization/compaction/insufficient BMP's**