

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 9258 From entrance to location



Photo # 9259 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667




Photo # 9260 Location



Photo # 9261 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 9262 Location



Photo # 9263 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 9264 Location



Photo # 9265 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



**Photo # 9266 Tank improperly labeled/lacks required information**



**Photo # 9267 Tank improperly labeled/lacks required information**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 9268 Open ended load line