

Inspection Photos


Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 12/11/2023



Location Entrance – Photo #08082



Wellheads – Photo #08085

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 12/11/2023



Separators – Photo #08083



Tank Battery – Photo #08086



Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 12/11/2023



Lack of Stabilization – Photo #08087



Lack of Stabilization – Photo #08088

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 12/11/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08090**



Unsecured Separator – Photo #08084