

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Location Overview: Location is within Black Bear Habitat area & in close proximity to High Priority/Density/NSO Habitat areas. Location is within Rule 411a Surface Water Intermediate Buffer. Location is approximately 379 yards from Beaver Creek.

Section/Township/Range: 1 7S94W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9103 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9104 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9105 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9106 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9107 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9108 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9109 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9110 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9111 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9112 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9113 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9114 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9115 Lack of stabilization/compaction/insufficient BMP's on location



Photo # 9116 Lack of stabilization/compaction/insufficient BMP's on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9117 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location



Photo # 9118 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9119 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location



Photo # 9120 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 9121 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location



Photo # 9122 Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location