

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2023

Submitted Date:

12/08/2023

Document Number:

708200749

**FIELD INSPECTION FORM**Loc ID 431539 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431538	WELL	PR	06/01/2021	OW	123-36657	Timbro LC13-76HN	RI
431539	LOCATION	AC			-	Timbro LC13-77-1HN Pad	RI
431540	WELL	TA	02/01/2021	OW	123-36658	Timbro LC13-75HN	RI
431541	WELL	PR	11/01/2020	OW	123-36659	Timbro LC13-76-1HN	RI
431542	WELL	PR	11/01/2020	OW	123-36660	TIMBRO LC13-77-1HN	RI

**General Comment:**[This is an Interim Reclamation and Stormwater Inspection for Location ID \(431539\).](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Day tank labels at wellheads are not legible (e.g. cracked, peeling, faded). Refer to attached inspection photos.		
Corrective Action:	Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023

Emergency Contact Number:

Comment:

Corrective Action:  Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Porta-john is not properly anchored and has drifted off into interim areas. Refer to attached inspection photos.		
Corrective Action:	Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023
Type	TRASH		
Comment:	Trash and debris observed throughout the location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>431538</u>	Type:	<u>WELL</u>	API Number:	<u>123-36657</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431539</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431540</u>	Type:	<u>WELL</u>	API Number:	<u>123-36658</u>	Status:	<u>TA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431541</u>	Type:	<u>WELL</u>	API Number:	<u>123-36659</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431542</u>	Type:	<u>WELL</u>	API Number:	<u>123-36660</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>

Environmental	
<b>Spill/Remediation:</b>	
Comment:	Remediation Project #30588 is still active and open. Continue to comply with 900 series rules and regulations.
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment: <div></div>	
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
<b>RESTORATION AND REVEGETATION</b>	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced <u>Pass</u>	Recontoured <u>Pass</u> 80% Revegetation <u>In</u>
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? <u>P</u>	
Comment	Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas is progressing towards Rule 1003 standards and will need to be re-inspected during the next growing season to verify vegetative compliance; therefore, the location will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.
Corrective Action	
Date _____	
Overall Interim Reclamation <u>In Process</u>	
<b><u>Final Reclamation/ Abandoned Location:</u></b>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: <u>RANGELAND</u>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads <u>Regraded</u> _____	Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. During this inspection, a stockpile of soil was observed on the eastern side of the production area; it is unknown if the material is impacted or not, as there were no signs/markers observed. Additionally, there were no temporary control measures around the base of the stockpile and the material is not properly stabilized against wind and water erosion as it is comprised of unconsolidated materials. Additional control measures are needed to contain and stabilize the stockpile. Refer to attached inspection photo.

Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403619964	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351238</a>
708200754	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351226</a>