

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2023

Submitted Date:

12/18/2023

Document Number:

696305528**FIELD INSPECTION FORM**Loc ID 435653 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435649	WELL	SI	08/01/2022	OW	123-38705	Antelope O34-K31-18HNC	SI
435650	WELL	SI	05/01/2023	OW	123-38706	Antelope Y44-U41-18HNC	SI
435651	WELL	PR	06/28/2022	OW	123-38707	Antelope T44-P41-18HC	PR
435652	WELL	PR	10/01/2022	OW	123-38708	Antelope T34-P31-18HNB	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical Container at Gas Lift Injection Meter House is missing labels; labels have weathered away no longer visible. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/19/2024
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Chemical Containers at South Side on Location. See photos		
Corrective Action:	Comply with Rule 606	Date:	01/19/2024

Overall Good: ☐**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

corrective date

Type: Bradenhead	# 4	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: Gas Meter Run	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 435649 Type: WELL API Number: 123-38705 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI - Since 08.01.2022

Corrective Action: _____

Date: _____

Facility ID: 435650 Type: WELL API Number: 123-38706 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI - Since 05.01.2023

Corrective Action: _____

Date: _____

Facility ID: 435651 Type: WELL API Number: 123-38707 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

Facility ID: 435652 Type: WELL API Number: 123-38708 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Seeding						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Chemical Container at Gas Lift Meters missing Labels. Unused Chemical Container at South Side of Location	petrie	12/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305529	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359372