

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2023

Submitted Date:

12/18/2023

Document Number:

709700286

FIELD INSPECTION FORMLoc ID 320211 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 3990

Name of Operator: ARGONEX COMPANY LLC

Address: PO BOX 810

City: SEDALIA State: CO Zip: 80135

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
HARTMAN, LARRY	936-590-1179	EHGriffith@aol.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203066	WELL	PR	08/01/2021	OW	001-08472	CHAMPLIN (HER) 1-1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: No Answer

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606		
Corrective Action:	Remove per Rule 606	Date:	01/19/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Cattle Fence		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		39.998861,-104.342196	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Berms around tanks in disrepair				
Corrective Action:	Maintain berms around tanks. Per Rule 603.o.(1) Corrective Action Date 30 days. See attached photos				Date: 01/19/2024

Wells Served By Facilities Above

API Number
001-08472

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	YES		
Comment:	Venting out of riser behind production tanks. This is issue was addressed on the last Inspection DOC#700901714. Still venting. OPGAL Camera video attached.		
Corrective Action:	Per Rule 903.d.(2) Cease Venting Immediately. See attached OPGAL Camera Video		Date: 12/19/2023

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203066 Type: WELL API Number: 001-08472 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment

COGCC Inspection Report Summary
 On (12/13/2023) at approximately (11:24am). I, Inspector Keith Huck, conducted an on-site inspection.
 Operator: Argonex Company LLC
 Location name: Champlin (HER)#1-1
 API # 001-08472
 Location ID #: 320211
 County: Adams
 While there, I observed a (SI) well.
 During this inspection the following possible compliance issues were observed:
 Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606
 Remove per Rule 606
 Berms around tanks in disrepair
 Maintain berms around tanks. Per Rule 603.o.(1) Corrective Action Date 30 days. See attached photos
 Venting out of riser behind production tanks. This issue was addressed on the last Inspection DOC#700901714. Still venting. OPGAL Camera video attached.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

User

huckk

Date

12/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709700287	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360610
709700288	OPGAL Camera Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360611