

Inspection Photos

12/18/2023

Operator: ANSCHUTZ EXPLORATION CORP

#3104

Location ID: 430927

Inspection Doc: 696205473

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 1: Photo shows Location entrance on the southeast end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 2: Photos 2-3 taken from the southeast end of the Location (Location entrance). Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



44° NE
December 18, 2023

Photo 4: Photos 4-6 taken from the western corner of the current working pad surface. Photo shows areas of the Location not reasonable needed for production, requiring reclamation pursuant to Rule 1003.b. Operator is currently storing various unused equipment within these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 6: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 7: Photos 7-8 taken from the east ends of the Location. Photos shows a second access road constructed on the Location; Road is ~800 feet and unnecessary.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: ANSCHUTZ EXPLORATION CORP #3104
Location ID: 430927



Photo 9: Photos show incorrect Operator information at tank battery and wellhead sign.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 10: Photos 10-11 taken from the southern corner of the Location. Photo shows spill at the “water pump” risers.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927





Photo 11: See comments under photo 10.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 12: Photo taken from the tank battery facility. Photo shows crack at the “recycling line”, resulting in a leak/spill.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 13: Photos example of stained soils observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 14: Photos example showing lines at tanks have not been capped/plugged. Photo also shows produced fluids have spilled into the honeypots.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
SCHUTZ EXPLORATION CORP #3104
Location ID: 430927




Photo 15: Photos 15-16 example showing wildlife protection measures to prevent wildlife ingress, and to allow for egress (such as netting, or escape ramps) are missing from containment measures at tanks on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 16: See comments under photo 15. Photo right also shows the containment BMP has cracked, and is no longer in proper functioning condition. Photo also example showing various trash/debris observed throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 17: Photos taken from the topsoil stockpile on the east end of the Location. Vegetation observed established on the stockpile is predominantly Undesirable Plant Species. BMPs to prevent the spread or establishment of weeds are inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 18: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 19: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 20: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 21: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 22: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 23: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 24: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 25: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 26: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 27: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



Photo 28: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430927



41° NE
December 18, 2023

Photo 29: Various trash/debris/unused equipment/container/etc... observed improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources