

Interim Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 421829

Inspection Document #: 708200738

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 1. Stained soil observed near loadout line at tank battery.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 2. Erosion degradation (rilling) occurring on the eastern portion of the production areas.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 3. Continued from photo 3, facing south. See comments in Photo 2.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photos 4-6. Animal burrows observed around the eastern and southern edges of the tank battery secondary containment.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 7. Taken from the northeast corner of the fenced production area. Interim reclamation activities appear to have been performed and areas within the fenced portion appear to be progressing towards Rule 1003 vegetation standards.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 8. Taken from the northeast corner of the production areas, facing northwest into reclaimed portions. The red highlight illustrates undesirable vegetation (e.g. russian thistle) within the interim areas. Additional weed management is required to comply with Rule 1003.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photo 9. Taken from the northwest corner of the production areas, facing north into the reclaimed interim areas. See comments in Photo 8.

Inspection Photos
Location Name: Fiscus Mesa 15-17H
Location ID: 421829



Photos 10 & 11. Erosion degradation (rilling) occurring within the center portion of the production areas.