

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2023

Submitted Date:

12/19/2023

Document Number:

696305539

FIELD INSPECTION FORMLoc ID 418009 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		Inspections@civiresources.co m	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418001	WELL	TA	03/21/2019	GW	123-31808	Antelope 19C	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Separator Fittings, Pipe, and Parts at Separators. See photos		
Corrective Action:	Comply with Rule 606	Date:	01/19/2024
Type	UNUSED EQUIPMENT		
Comment:	Unmarked OOSLAT Risers at Wellhead, ECD and Separator. See photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	12/22/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical Container at Separators		
Corrective Action:	Comply with Rule 606	Date:	01/19/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Horizontal Heated Separator	# 2			
Comment: Both Separators are open to Atmosphere.				
Corrective Action: All open ended Pipe, Valves and Heat Stacks shall be covered. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 12/22/2023		
Type: Bradenhead	# 1			
Comment: Appears to be plumbed to surface				
Corrective Action:		Date:		
Type: Other	# 1			
Comment: TA Wellhead				
Corrective Action:		Date:		
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares berm with the Crude Oil Tanks					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.380140,-104.370470
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: PETRIE, ERICA

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 418001 Type: WELL API Number: 123-31808 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 03.21.2019. MIT - 03.25.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary:</p> <p>On Tuesday 12/12/2023 at approximately 14:23. I, Compliance Specialist, Erica Petrie, conducted an on-site Inspection at: Operator Name: Bonanza Creek Energy Operating Company LLC Location Name: Antelope 19C Location ID: 418009 Location County: Weld County, Colorado While there, I observed: Well - 1: Temporarily Abandon Entire Battery and Equipment are Shut-Down.</p> <p>While there, I observed Production Operations During this Inspection the following possible Compliance Issues were observed:</p> <p>Well is TA - Since 03.21.2019. MIT - 03.25.2021. On Form 6A 403213997 List with a Plug Due Date of 12.31.2023</p> <p>Unused Separator Fittings, Pipe, and Parts at Separators. See photos. Comply with Rule 606. Corrective Action Date 01.19.2024</p> <p>Unused Chemical Container at Separators. See photos. Comply with Rule 606. Corrective Action Date 01.19.2024</p> <p>Unmarked OOSLAT Risers at Wellhead, ECD and Separator. See photos. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. Corrective Action Date 12.22.2023</p> <p>Both Separators are open to Atmosphere. All open ended Pipe, Valves and Heat Stacks shall be covered. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b. Corrective Action Date 12.22.2023</p> <p>A follow up on this Site Inspection will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules.</p> <p>This is a summary of the Inspection Report.</p>	petrie	12/18/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696305540	Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362571