

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CLOUGH-66S95W/33NESW

Location ID: 335292

Date: 12/18/2023



Wellheads – Photo #08282



Separators – Photo #08279

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CLOUGH-66S95W/33NESW

Location ID: 335292

Date: 12/18/2023



Tank Battery – Photo #08276



Lack of Stabilization – Photo #08285

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CLOUGH-66S95W/33NESW

Location ID: 335292

Date: 12/18/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08286