

Interim Reclamation and Stormwater Inspection

Date: 12/7/23

Operator: PDC Energy Inc. - 69175

Location ID: 459972

Inspection Document #: 713900161

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972



Photo 1. The photo was taken at the well location entrance facing Southeast. The photo illustrates the entrance gates and some operator signage.

Photo 2. The photo was taken from the well location facing East. The photo illustrates the southeast portion of the interim areas are dominated in places by kochia.

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972



Photo 3. The photo was taken at the well location entrance facing Southeast. The photo illustrates the entrance gates and some operator signage.

Photo 4. The photo was taken at the well location facing South. The photo illustrates the interim area between the tank battery and O&G equipment and the wellheads with good perennial cover in this area.

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972



Photo 5. The photo was taken at the well location facing South. The photo illustrates a large stand of kochia growing in the Southeast area of the interim reclamation area.

Photo 6. The photo was taken at the well location facing East. The photo illustrates cattle grazing inside the location fencing.

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972



Photo 7. The photo was taken at the well location facing Northwest. The photo illustrates a temporarily stabilized outlet through the perimeter gravel berm. The BMP will need some maintenance as stakes and wattle are sedimented and beginning to fall apart potentially due to cattle.

Photo 8. The photo was taken at the well location facing Northwest. The photo illustrates a large patch of interim reclamation that still does not appear to be growing.

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972



Photo 9. The photo was taken at the well location facing South. Refer to the comment for photo 7.



Photo 10. The photo was taken at the well location facing Northeast. The photo illustrates a small patch of stained soil that smelled of diesel.

Inspection Photos
Location Name: Sunlight 5N64W8 1-11
Location ID: 459972




Photo 11. The photo was taken using Weld County 2022 aerial imagery. The photo illustrates a two-track cutting through interim areas on the well location.