

# Inspection Photos

API: 043-06157

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 12/21/2023

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the location. There is a plastic bucket covering an open wellbore at red arrow.



## Inspection Photos



**Photo 2.** There is a well casing and deep wellbore which the plastic bucket was covering. This need to be immediately covered and plugged and abandoned..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334402 | Date: 12/21/2023

## Inspection Photos



**Photo 3.** Facing back east at the location. There is a plastic bucket covering an open wellbore at red arrow.



## Inspection Photos



**Photo 4.** Facing south at the west side of the location. There is an exposed electric line at red arrow and multiple open pipe risers. All risers and utilities need to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334402 | Date: 12/21/2023

## Inspection Photos



**Photo 5.** There are unused pipe risers that need to be abandoned and removed.



## Inspection Photos



**Photo 6.** Facing back east at the location. There is a plastic bucket covering an open wellbore at red arrow.

