

Inspection Photos

Loc: 322241

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 12/21/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite location.



Inspection Photos



Photo 2. Facing east by the separator. There was an attempt to repair the erosion however this area needs to be properly stabilized.



Inspection Photos



Photo 3. Facing southeast at west side of the location. The perimeter one wire fence is not maintained and needs to be removed or a proper fence installed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322241 | Date: 12/21/2023

Inspection Photos



Photo 4. Facing east at the wellsite.



Inspection Photos



Photo 5. There is a one wire fence at the location which is not maintained and is not highly visible and could pose a collision hazard..

