

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2023

Submitted Date:

12/22/2023

Document Number:

713600524

FIELD INSPECTION FORM

Loc ID 417859 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10417
 Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
 Address: 113 N SANTA FE AVE
 City: FLORENCE State: CO Zip: 81226

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	
Harkins, Liz		lharkins@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417858	WELL	PR	06/01/2020	OW	043-06194	Woolly Bugger 34-20	RI

General Comment:

This is a reclamation inspection of the Woolly Bugger #34-20 wellsite.
 See attached photos and additional details within this report.

The date of discovery is given for all new corrective action dates. It is ECMC's expectation that Operators are in compliance with ECMC rules at all times. Therefore, No extended CA dates are applied and the corrective action will remain out of compliance until completed.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	There is no sign at the offsite tank battery		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 12/21/2023

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	There are weed debris inside the offsite tank battery.		
Corrective Action:	Comply with Rule 606.		Date: 12/21/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No		
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type:	Flow Line	#	
Comment:	The flowline is not registered to the offsite tank battery.		
Corrective Action:	Submit an eForm 44 Flowline Report per Rule 1101.a.		Date: 12/21/2023

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600525	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6369683