

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2023

Submitted Date:

12/22/2023

Document Number:

694100242**FIELD INSPECTION FORM**Loc ID 311389 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
,		cogccinspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 311389 Ikenouye F29 TB and WH. Any corrective actions from previous inspections that have not been addressed are still applicable. There were operator and contract environmental personnel on location at the time of this field inspection. Crews were hydrvaccing groundwater out of an open wellhead excavation and were planning to do another excavation as well as remove two underground vaults near where the tank battery used to be. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment:

unused hoses on location. Need to be picked up.

Statewide unnecessary equipment, weeds, waste, and trash requirements.

Corrective Action:

Comply with Rule 606

Date: 01/12/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

Comment:

Control and contain spills/releases and clean up per Rule 912.a.

Corrective Action:

Control and contain spills/releases and clean up per Rule 912.a.

Date: 01/05/2024

In Containment: No

Comment:

Onsite crew indicated that a spill had occurred at the wellhead. Hydrovac activity was occurring at the time of inspection. Soil samples had been taken and there were plans for more at an adjacent wellhead.

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 311389 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: unlined soil stock pile on location. Site Preparation and Stabilization.

Corrective Action: Needs to be removed, or lined and contained with erosion control BMP. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/05/2024

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Onsite crew indicated that a spill had occurred at the wellhead. Hydrvoacccing activity was occurring at the time of inspection. Soil samples had been taken and there were plans for more at an adjacent wellhead.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
There were operator and contract environmental personnel on location at the time of this field inspection. Crews were hydrvaccing groundwater out of an open wellhead excavation and were planning to do another wellhead excavation as well as remove two underground vaults near where the tank battery used to be. Samples have been taken.	robinsotl	12/22/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100243	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370238