

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422



Photo # 188 From entrance to location



Photo # 189 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422




Photo # 190 Location



Photo # 191 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422



Photo # 192 Location

Photo # 193 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422



Photo # 194 Location




Photo # 195 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422



Photo # 196 Barbed wire on ground/wildlife hazard



Photo # 197 Barbed wire on ground/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad

Location # 324422



Photo # 198 Hole in liner/liner needs maintenance



Photo # 199 Hole in liner/liner needs maintenance