

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



**Location Overview: Location is within High Priority/Black Bear
Habitat areas & in close proximity to Density Habitat area.
Location is approximately 260 yards from Porcupine Creek.
Section/Township/Range: 11 7S94W**



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 200 Lack of stabilization/compaction/ insufficient BMP's



Photo # 201 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 202 Lack of stabilization/compaction/insufficient BMP's



Photo # 203 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 204 Lack of stabilization/compaction/insufficient BMP's



Photo # 205 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 206 Lack of stabilization/compaction/insufficient BMP's



Photo # 207 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 208 Lack of stabilization/compaction/insufficient BMP's



Photo # 209 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 210 Lack of stabilization/compaction/insufficient BMP's



Photo # 211 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 212 Lack of stabilization/compaction/insufficient BMP's



Photo # 213 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Dec 19, 2023 at 12:12:23 PM

Photo # 214 Lack of stabilization/compaction/insufficient BMP's



Dec 19, 2023 at 12:12:33 PM

Photo # 215 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 216 Lack of stabilization/compaction/insufficient BMP's



Photo # 217 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 218 Lack of stabilization/compaction/insufficient BMP's



Photo # 219 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 220 Lack of stabilization/compaction/insufficient BMP's



Photo # 221 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 222 Lack of stabilization/compaction/insufficient BMP's



Photo # 223 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 11-13A (RM11) Pad
Location # 324422



Photo # 224 Lack of stabilization/compaction/insufficient BMP's



Photo # 225 Lack of stabilization/compaction/insufficient BMP's