

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2023

Submitted Date:

12/18/2023

Document Number:

709700286**FIELD INSPECTION FORM**Loc ID 320211 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 3990

Name of Operator: ARGONEX COMPANY LLC

Address: PO BOX 810

City: SEDALIA State: CO Zip: 80135

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
HARTMAN, LARRY	936-590-1179	EHGriffith@aol.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203066	WELL	PR	08/01/2021	OW	001-08472	CHAMPLIN (HER) 1-1	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	No Answer		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606		
Corrective Action:	Remove per Rule 606	Date:	01/19/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Cattle Fence		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.998861,-104.342196
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms around tanks in disrepair			
Corrective Action:	Maintain berms around tanks. Per Rule 603.o.(1) Corrective Action Date 30 days. See attached photos			Date: 01/19/2024

**Wells Served By Facilities Above**

API Number
001-08472

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	YES	
Comment:	Venting out of riser behind production tanks. This is issue was addressed on the last Inspection DOC#700901714. Still venting. OPGAL Camera video attached.	
Corrective Action:	Per Rule 903.d.(2) Cease Venting Immediately. See attached OPGAL Camera Video	Date: 12/19/2023

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 203066 Type: WELL API Number: 001-08472 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On (12/13/2023) at approximately (11:24am). I, Inspector Keith Huck, conducted an on-site inspection.  Operator: Argonex Company LLC  Location name: Champlin (HER)#1-1  API # 001-08472  Location ID #: 320211  County: Adams  While there, I observed a (SI) well.  During this inspection the following possible compliance issues were observed:  Weeds, dead weeds, trash, debris &amp; unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606  Remove per Rule 606  Berms around tanks in disrepair  Maintain berms around tanks. Per Rule 603.o.(1) Corrective Action Date 30 days. See attached photos  Venting out of riser behind production tanks. This is issue was addressed on the last Inspection DOC#700901714. Still venting. OPGAL Camera video attached.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	huckk	12/18/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403628772	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360632</a>
709700287	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360610">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360610</a>
709700288	OPGAL Camera Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360611">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360611</a>