

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2023

Submitted Date:

12/18/2023

Document Number:

713600494

**FIELD INSPECTION FORM**

Loc ID 416357 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed		ed@renegadeoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446543	TANK BATTERY	AC	07/08/2016		-	IDLER B 2X	RI

**General Comment:**

[This is a follow up of the previous reclamation inspections #690204420, #713600206. See attached photos and additional details within this report.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	There is no sign posted at the offsite tank battery. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.e	Date:	07/11/2023

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: It appears stained soils previously observed were cleaned up.

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	A berm has been installed around the tank. The soil berms need to be compacted to be impervious.			
Corrective Action:				Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403627624	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359436</a>
713600495	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359435">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359435</a>