

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2023

Submitted Date:

12/19/2023

Document Number:

696305539

FIELD INSPECTION FORMLoc ID 418009 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | Inspections@civiresources.com | |
| Gomez, Jason | | jason.gomez@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 418001 | WELL | TA | 03/21/2019 | GW | 123-31808 | Antelope 19C | TA |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Chemical Container at Separators | | |
| Corrective Action: | Comply with Rule 606 | Date: | 01/19/2024 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unmarked OOSLAT Risers at Wellhead, ECD and Separator. See photos | | |
| Corrective Action: | Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. | Date: | 12/22/2023 |
| Type | STORAGE OF SUPL | | |
| Comment: | Unused Separator Fittings, Pipe, and Parts at Separators. See photos | | |
| Corrective Action: | Comply with Rule 606 | Date: | 01/19/2024 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

| | | | | |
|---|-----|--|--|------------------|
| Equipment: | | | | corrective date |
| Type: Other | # 1 | | | |
| Comment: TA Wellhead | | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: Appears to be plumbed to surface | | | | |
| Corrective Action: | | | | Date: |
| Type: Emission Control Device | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | | |
| Comment: Both Separators are open to Atmosphere. | | | | |
| Corrective Action: All open ended Pipe, Valves and Heat Stacks shall be covered. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b. | | | | Date: 12/22/2023 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 60 BBLS |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|---|----------|---------------------|---------------------|-------------|-----------------------|
| | | | | | |
| Comment: Shares berm with the Crude Oil Tanks | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.380140,-104.370470 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

Inspector Name: PETRIE, ERICA

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 418001 Type: WELL API Number: 123-31808 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 03.21.2019. MIT - 03.25.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary:</p> <p>On Tuesday 12/12/2023 at approximately 14:23. I, Compliance Specialist, Erica Petrie, conducted an on-site Inspection at: Operator Name: Bonanza Creek Energy Operating Company LLC Location Name: Antelope 19C Location ID: 418009 Location County: Weld County, Colorado While there, I observed: Well - 1: Temporarily Abandon Entire Battery and Equipment are Shut-Down.</p> <p>While there, I observed Production Operations During this Inspection the following possible Compliance Issues were observed:</p> <p>Well is TA - Since 03.21.2019. MIT - 03.25.2021. On Form 6A 403213997 List with a Plug Due Date of 12.31.2023</p> <p>Unused Separator Fittings, Pipe, and Parts at Separators. See photos. Comply with Rule 606. Corrective Action Date 01.19.2024</p> <p>Unused Chemical Container at Separators. See photos. Comply with Rule 606. Corrective Action Date 01.19.2024</p> <p>Unmarked OOSLAT Risers at Wellhead, ECD and Separator. See photos. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. Corrective Action Date 12.22.2023</p> <p>Both Separators are open to Atmosphere. All open ended Pipe, Valves and Heat Stacks shall be covered. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b. Corrective Action Date 12.22.2023</p> <p>A follow up on this Site Inspection will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules.</p> <p>This is a summary of the Inspection Report.</p> | petrie | 12/18/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403631011 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362628 |
| 696305540 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362571 |