

Interim Reclamation and Stormwater Inspection

Date: 12/20/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 421062

Inspection Document #: 708200774

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 1. Cattle panels and wire/cable do not appear to be in use.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photos 2 & 3. Day tank secondary containment units at wellhead do not have adequate wildlife protection equipment (e.g. netting).

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



12/20/23, 11:35 AM
80° E
ECMC

Photo 4. Northern interim areas appear to be progressing towards Rule 1003 standards and regulations with the presence of desirable species observed. A follow-up inspection will be conducted at a later date during the active growing season to verify vegetation compliance with Rule 1003.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 5. Northern interim areas, facing west. See comments in Photo 4.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 6. Southern interim areas, facing west. See comments in Photo 4.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 7. Southern interim areas, facing east. See comments in Photo 4.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 8. Taken from the top of the topsoil stockpile, facing south. Photo illustrates that the topsoil stockpile is predominantly undesirable vegetation (e.g. kochia and russian thistle). Additional weed management and/or reseeding activities are required in order to comply with Rule 1002.c.

Inspection Photos
Location Name: State 8-60 16-1H
Location ID: 421062



Photo 9. Topsoil stockpile, facing north. See comments in Photo 8.