

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Photo # 749 From entrance to location



Photo # 750 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Dec 26, 2023 at 11:11:51 AM



Dec 26, 2023 at 11:17:58 AM

Photo # 751 Location

Photo # 752 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Photo # 753 Location



Photo # 754 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Photo # 755 Location



Photo # 756 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Dec 26, 2023 at 11:27:52 AM

Photo # 757 Location



Dec 26, 2023 at 11:33:27 AM

Photo # 758 Cap not covering PRV vent line on test separator

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Photo # 759 PRV vent line on test separator lacks cap



Photo # 760 PRV vent line on test separator lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Dec 26, 2023 at 11:12:39 AM

Photo # 761 Wellheads lack required signage



Dec 26, 2023 at 11:13:43 AM

Photo # 762 Wellheads lack required signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE C29 Pad

Location #: 335692



Photo # 763 Debris