

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/13/2023

Submitted Date:

12/22/2023

Document Number:

694100242

**FIELD INSPECTION FORM**

Loc ID 311389 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	<a href="#">All PDC inspection</a>
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID 311389 Ikenouye F29 TB and WH. Any corrective actions from previous inspections that have not been addressed are still applicable. There were operator and contract environmental personnel on location at the time of this field inspection. Crews were hydrvaccing groundwater out of an open wellhead excavation and were planning to do another excavation as well as remove two underground vaults near where the tank battery used to be. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: unused hoses on location. Need to be picked up.  
Statewide unnecessary equipment, weeds, waste, and trash requirements.

Corrective Action: **Comply with Rule 606**

Date: 01/12/2024

Overall Good:

**Spills:**

Type

Area

Volume

Comment: Control and contain spills/releases and clean up per Rule 912.a.

Corrective Action: **Control and contain spills/releases and clean up per Rule 912.a.**

Date: 01/05/2024

In Containment: No

Comment: Onsite crew indicated that a spill had occurred at the wellhead. Hydrovac activity was occurring at the time of inspection. Soil samples had been taken and there were plans for more at an adjacent wellhead.

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 311389 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** unlined soil stock pile on location. Site Preparation and Stabilization.

**Corrective Action:** Needs to be removed, or lined and contained with erosion control BMP. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/05/2024

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Onsite crew indicated that a spill had occurred at the wellhead. Hydrvoacccing activity was occurring at the time of inspection. Soil samples had been taken and there were plans for more at an adjacent wellhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
There were operator and contract environmental personnel on location at the time of this field inspection. Crews were hydrvaccing groundwater out of an open wellhead excavation and were planning to do another wellhead excavation as well as remove two underground vaults near where the tank battery used to be. Samples have been taken.	robinsotl	12/22/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403635449	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370253</a>
694100243	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370238</a>