

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2023

Submitted Date:

12/22/2023

Document Number:

710500148

FIELD INSPECTION FORMLoc ID 307777 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256807	WELL	PR	06/20/2001	CBM	071-06943	CELICA 32-26	EI
257670	PIT	AC			-	BENTLEY-CELICA OFFSITE 14-24 TR	EI
307777	LOCATION	AC			-	CELICA-632S67W 26SWNE	EI

General Comment:

This is a follow-up Environmental Inspection to inspection #710500084 for the Celica 32-23, Facility # 307777, active well location located in Las Animas County Colorado.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Shed remains on location located near the wellhead, Original CA from Inspection # 710500084 still applies		
Corrective Action:	Unused Equipment. Comply with Rule 606.	Date:	12/06/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:	Rig Anchors not properly marked, Operator did reset anchor markers to comply with Original CA date however, anchor markers have since fallen.		
Corrective Action:	Comply with Rule 603.j.	Date:	01/25/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>256807</u>	Type: <u>WELL</u>	API Number: <u>071-06943</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>257670</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	------------------	----------------------	-------------------	-------------------------

Facility ID: <u>307777</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

COGCC Comments

Comment	User	Date
At the time of inspection Pit Freeboard was maintained.	sanchezcc	12/22/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403634977	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6369777
710500149	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6369754