

Reclamation Corrective Action Inspection		
Date of Inspection	12/18/2023	
Inspector Name	Levi Johnson, Farroxx DS	
Location Name	Duncan D 11-14	
COGCC Lic ID	329529	
County	Weld	
Location Direction	KERSEY FROM INTERSECT CR 53 AND CR 34 GO E/2.44 MI TO ACCESS RD CONT N/NW/1.1 MI ON ACCESS RD THEN CONT W/.05 MI TO WELL SITE DUNCAN D 11-14 @ GPS PT (40.233997, -104.521229)	
Woods or Debris	Location is mowed, annual and perennial vegetation is evident	
Visual Evt. of Vegetative	Location is in final reclamation phase, perennial vegetation beginning to establish	
Stormwater	No stormwater issues observed	
Additional Notes	none	
Recommendations	Monitor establishment of perennial grasses and forbs, implement weed control plan and mowing for annual weeds	
Reclamation/Stormwater Corrective Action Procedure	In response to ECOMC Inspection 713900102, location was mowed and innerseeded with Sandy Loam Native Mix applied at 20 lbs/acre.	
Photos	Below, show that mowing and innerseeding have been done	
		
 <p>From start of access road facing SSW</p>		
 <p>From center of pad facing N</p>	 <p>From center of pad facing E</p>	 <p>From center of pad facing S</p>
 <p>From center of pad facing W</p>	 <p>From end of access road facing SSE</p>	