

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



Photo # 1318 From entrance to location



Photo # 1319 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804




Photo # 1320 Location




Photo # 1321 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



Photo # 1322 Location




Photo # 1323 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



Photo # 1324 Location



Photo # 1325 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



Photo # 1326 Location



Photo # 1327 Wellhead sign lacks required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



Photo # 1328 Wellhead sign lacks required info



Photo # 1329 Wildlife protection on chemical tank containment needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad

Location #: 335804



**Photo # 1330 Wildlife protection on chemical tank
containment needs maintenance**

