

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1052 From entrance to location



Photo # 1053 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1054 Location



Photo # 1055 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1056 Location/blowdown tank



Photo # 1057 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Dec 28, 2023 at 10:55:26 AM

Photo # 1058 Location



Dec 28, 2023 at 10:58:15 AM

Photo # 1059 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1060 Location



Photo # 1061 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1062 Location



Photo # 1063 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1064 PRV vent line on test separator lacks cap




Photo # 1065 PRV vent line on test separator lacks cap



Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1066 Hole in ground near wellheads/wildlife & personnel protection insufficient



Photo # 1067 Wellhead signs lack required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1068 Wellhead signs lack required information



Photo # 1069 Wellhead signs lack required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1070 Wellhead signs lack required information



Photo # 1071 Wellhead signs lack required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807




Photo # 1072 Debris



Photo # 1073 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807



Photo # 1074 Debris



Photo # 1075 Wildlife protection on chemical tank containment needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EFO6B I30A 595 Pad

Location #: 335807




Photo # 1076 EF14D-19 well bradenhead line connected to flowline/no FORM 4 Sundry

