

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135



Photo #1

Amigo 17-12 (123-18484) Wellsite

Plugged & Abandoned | PA

Cut / Capped

Flowline is Locked-Out, Tagged-Out | LOTO ; OOSLAT

prior photo



Photo #2

Amigo 17-12 Battery site

Inactive | Shut-down

Formerly served:

Amigo 17-12, Gulley 17-15, Uhrich 17-21 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 330135

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135



Photo #3

Amigo 17-12 Battery site

Inactive | Shut-down

Tank(s): SE corner

prior photo

All wells have been PA'd; Remove Equipment

Form 27-I Remediation Workplan on file.



Photo #4

Amigo 17-12 Battery site

Inactive | Shut-down

ECD(s), Separator(s)

prior photo

All wells have been PA'd; Remove Equipment

Form 27-I Remediation Workplan on file.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135



Photo #5

Amigo 17-12 Battery site

Inactive | Shut-down

Battery sign

prior photo

All wells have been PA'd; Remove Equipment

Form 27-I Remediation Workplan on file.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources