

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



**Location Overview: Location is within High Priority/Density
Habitat areas & in close proximity to NSO Habitat area.
Location is approximately 138 yards from a creek/drainage
that contributes to the Colorado River.
Section/Township/Range: 17 6S94W**


Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1389 Culvert at entrance to location needs maintenance



Photo # 1390 Rip Rap Run needs maintenance, stormwater has eroded around both sides of BMP & there's sediment buildup in some areas of BMP (eastern side of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1391 Rip Rap Run needs maintenance, stormwater has eroded around both sides of BMP (eastern side of location)



Photo # 1392 Rip Rap Run needs maintenance (eastern side of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1393 Rip Rap Run needs maintenance (eastern side of location)



Photo # 1394 Berm needs maintenance/tunnel erosion & transport of sediment through berm & onto location (North area of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1395 Vehicle tracks observed traveling off the working pad area & into the interim area.



Photo # 1396 Rip Rap Run/BMP needs maintenance (N/NW area of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1397 Vehicle tracks observed traveling off the working pad area & into the interim area.



Photo # 1398 Stormwater BMP's along lease road need maintenance (Approximately 70-75 yards from entrance to location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC FEDERAL RMV 60-17 Pad
Location # 324076



Photo # 1399 Stormwater BMP's along lease road need maintenance (Approximately 75-80 yards from entrance to location)



Photo # 1400 Rip Rap Run/BMP needs maintenance (S/SE area of location)