

# Inspection Photos

Loc: 307766

Operator: WAPITI OPERATING LLC

Inspection Date: 1/2/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing northeast toward the access road and wellsite.



## Inspection Photos



**Photo 2.** Facing toward north side of the location. This area has been graded and soil is pushed out to the edge. This interim area will need to be reclaimed.



## Inspection Photos



**Photo 3.** Facing south at the west side of the location. Soil has been pushed out along the edge and will need to be pulled back..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307766 | Date: 1/2/2024

## Inspection Photos



**Photo 4.** There is an erosion channel at the northwest side of the location that needs to be repaired. Arrow points to 4.5 ft. shovel.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307766 | Date: 1/2/2024

Inspection Photos



**Photo 5.** There are other erosion channel along the cut slope which have snow cover..



Inspection Photos



**Photo 6.** Facing toward the cut slope which has sign of erosion that need to be repaired..



Inspection Photos



**Photo 7.** Northeast corner of the location. Soil has been pushed out from snow removal and will need to be replaced. Disturbance area will need to be reclaimed.



## Inspection Photos



**Photo 8.** The plastic pipe has been excavated and pipe fence guard is not in place. .

