

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2024

Submitted Date:

01/05/2024

Document Number:

708902701

FIELD INSPECTION FORM

Loc ID 324052 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211581	WELL	PR	10/01/2003	GW	045-07342	CHRISTNER 8-6 (F8E)	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 01/04/2024 at approximately 12:07 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) pad. Location # 324052 in Garfield County Colorado.
Please refer to inspection 708902439 conducted on 12/07/2023, previous corrective actions have been completed. Location is within High Priority/Density/NSO/Black Bear Habitat areas.
Location is approximately 125 yards from West Mamm Creek & 291 yards from Middle Mamm Creek. While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type SEPARATOR		
Comment:	Cattle panels		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	Cattle panels		
Corrective Action:			Date:

Equipment:		corrective date
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Pressure transducer located on bradenhead, bradenhead valve is accessible.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Telemetry	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Summit Midstream	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	Well on plunger lift	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Unlined containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211581 Type: WELL API Number: 045-07342 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse in sections
		Culverts				
				Material Handling And Spill Prevention		Chemical tank containment
Check Dams						
		Compaction				
		Ditches				
Ditches						
Gravel						Sparse in some areas
Rip Rap						
Compaction						Small areas of light compaction

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902702	Inspection 708902701 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383276
708902703	Inspection 708902701 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383277