

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Park 4-63-4 NE

Loc ID: 459857

Inspection: 699107965



Exhibit A

CA: Stained soil under appears to be leaking valve next to the tank needs to be removed. See attached photo. "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Operator has appropriately addressed and cleared identified stained soil to comply with Rule 905.e.



Exhibit A



Exhibit B

CA: Unmarked risers in multiple spots need to be marked with OOSLAT tags and Locked out/ Tagged out. See attached photos. Comply with the 1100 rules.

CA Resolution: Operator has appropriately marked identified Risers to comply with the Rule 1100 series.



Exhibit A

CA: Stained soil under appears to be leaking valve next to the lact needs to be removed. See attached photo. "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Operator has appropriately addressed and cleared identified stained soil to comply with Rule 905.e.

CA: Valve next to the lact appears to be leaking and needs to be fixed or replaced. See attached photo. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

CA Resolution: Operator has appropriately addressed the identified valve issue to comply with Rule 608.e.